



## PROPOLY - Exterior WATER-BASED POLYURETHANE

### PRODUCT CODES

PPEXT10 (FLAT)  
PPEXT30 (SATIN)  
PPEXT50 (SEMI-GLOSS)

### SIZES

4 L



Goudey **PROPOLY** Exterior water-based polyurethane provides professional grade protection for wood surfaces such as doors, windows, fences and furniture. Goudey **PROPOLY** Exterior is designed to protect from the sun's harmful UV rays and nature's elements. Goudey **PROPOLY** Exterior preserves the beauty of the wood and prevents cracking and peeling.

### PRODUCT ADVANTAGES

- Ideal for all exterior wood surfaces
- Low odour
- UV protection
- Protects against cracking, peeling and mould
- Easy soap and water clean-up

APPROVED COMPANION PRODUCTS	COATING PROPERTIES		DRY TIMES
W Series Wiping Stains	Viscosity (Krebs-Stomer)	58-62	1-3 hours at 21°C at 50% relative humidity. Drying time may vary based on temperature and relative humidity.
WB Series Water-Based Wiping Stains	Solids Content (wt.)	32%	
D Series Non Grian Raising Stains	Solids Content (volume)	30%	
	Theoretical Coverage	Up to 525 sq. ft/gal	
	Specific Gravity	1.03-1.04 kg/L	
	VOC (coating)	115 g/L	
	Shelf Life	12 months in a well sealed container	
	Storage	Minimum temperature at 5°C to a maximum of 35°C. KEEP FROM FREEZING. KEEP OUT OF REACH OF CHILDREN.	

## APPLICATION INSTRUCTIONS

### SUBSTRATE PREPARATION

- For previously finished surfaces: Remove old varnish, dirt, mildew, wax, grease and oil and sand with 180 grit sandpaper.
- For new wood, sand with 180 grit sandpaper.
- Ensure wood is dry and clear of sanding dust.

### APPLICATION

#### Recommended Conditions for Application

- Wood humidity level: <12%
- Temperature: 15° – 25° C (59° -77° F)
- Do not use in direct sunlight, at night or if rain is expected within 24 hours.

#### Application

1. Stir well before and during use.  
Do not shake.
2. If applying on stained or exotic woods, test for adhesion first.
3. Apply uniform coats following the wood grain with a good quality synthetic brush or spray gun.
4. Allow 1-3 hours to dry and lightly sand with 220 grit sandpaper between coats.
5. Repeat for 2 to 3 coats.
6. Allow 24 hours to dry before usage.

### PRECAUTIONS

**Clean-up:** Clean all tools with warm water and soap immediately after use.

**Storage:** Keep in dry area. AVOID FREEZING. KEEP OUT OF REACH OF CHILDREN.

**DISCLAIMER** These products are designed **for industrial use only**. Goudey views safety as a top priority. Please refer to the Safety Data Sheet for information on the safe use of this product. Values shown are calculated estimates and should not be construed as product specifications. We cannot anticipate all conditions under which this information and our products or the products of other manufacturers in combination with our products may be used. We accept no responsibility for results obtained by the application of this information or the safety and suitability of each such product or product combination for their own purposes. Unless otherwise agreed in writing, we sell the products without warranty, and users assume all responsibility and liability for loss or damage arising from the use of our products whether used alone or a combination with other products. Use of unapproved or reclaimed solvent blends may reduce film properties and is not recommended.